



The Standard

PROPELLER LOG

ASA-SP-L

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time in Service	Description
19 ____		MCASLEY MODEL 1A175 SH P80270
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Date	Total Time in Service	Description
0 ____		I have inspected the propeller and find it in satisfactory condition
Next Inspection Due:	Time Since Overhaul	
	278	Mech. Cert. # or Repair Station # Robert Phillips

Date	Total Time in Service	Description

Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____